

MATERIAL SAFETY DATA SHEET

SECTION I - IDENTITY INFORMATION

PRODUCT NAME: PRIME PLUG 1, 2, AND 3
MANUFACTURER: PRIME RESINS, INC.
2381 ROCKAWAY IND. BLVD.
CONYERS, GA 30012
EMERGENCY PHONE: 1-800-424-9300

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

HEALTH: 1
FLAMMABILITY: 0
REACTIVITY: 0
SPECIAL: 0

HAZARDOUS COMPONENTS:

MINERAL FILLERS OSHA PEL...ACGH TLV...OTHER LIMITS...%
FREE SIO2

NONE OF THE COMPONENTS OF THE MIXTURE ARE CONSIDERED HAZARDOUS MATERIALS
OR CARCINOGENS (1910-1200 HAZARD COMMUNICATION (D) (4))

TRANSPORTATION INFORMATION: NA

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT: NOT KNOWN TO BOIL
VAPOR PRESSURE (MM HG): NA
VAPOR DENSITY: NA
SOLUBILITY: NEGLIGIBLE
APPEARANCE: POWDER
SPECIFIC GRAVITY (H2O=1): 2.2
MELTING POINT: NA
EVAPORATION: NA

PRIME PLUG 1, 2, AND 3

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: NA
FLAMMABLE LIMITS: NA
EXTINGUISHING MEDIA: NA
SPECIAL FIRE FIGHTING PROCEDURES: NA
UNUSUAL FIRE & EXPLOSION HAZARDS: NA

SECTION V - REACTIVITY DATA

STABILITY: STABLE
CONDITIONS TO AVOID: NONE
INCOMPATIBILITY (MATERIAL TO AVOID): NONE
HAZARDOUS DECOMPOSITION (BY-PRODUCTS): NONE
HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

SECTION VI - HEALTH HAZARD DATA

ROUTES OF ENTRY: INHALATION - YES
 SKIN - NO
 INGESTION - NO

HEALTH HAZARDS (ACUTE & CHRONIC):

SKIN CONTACT: NA
EYE CONTACT: NA
INHALATION: REPEAT INHALATION OF RESPIRABLE DUST FOR
 EXTENDED PERIODS OF TIME MAY CAUSE INJURY
 TO LUNGS
INDIGESTION: NA
CARCINOGENICITY: NA
NTP: NO
IARC MONOGRAPHS: NO
OSHA REGULATED: NO

SIGNS AND SYMPTOMS OF EXPOSURE:

REPEATED INHALATION OF RESPIRABLE DUST FOR EXTENDED PERIODS OF
TIME MAY CAUSE INJURY TO THE LUNGS (SILICOSIS)

EMERGENCY AND FIRST AID PROCEDURES:

SKIN: WASH THOROUGHLY WITH SOAP AND WATER
EYES: FLUSH WITH WATER FOR 15 MINUTES - CALL PHYSICIAN
INHALATION: NA
INGESTION: NA

PRIME PLUG 1, 2, AND 3

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: AVOID EXCESSIVE DUSTING.

WASTE DISPOSAL METHOD: PREFERRED PROCEDURE IS TO VACUUM MATERIAL. OTHERWISE: SPRAY WITH WATER AND CLEAN UP WITH BROOM AND SHOVEL. DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: AVOID PROLONGED CONTACT WITH SKIN SURFACE. SKIN CONTACTED FOR PROLONG PERIODS SHOULD BE WASHED THOROUGHLY WITH SOAP AND WATER.

SECTION VIII - CONTROL MEASURES

RESPIRATORY PROTECTION:	NIOSH APPROVED RESPIRATORY PROTECTION FOR DUSTY ENVIRONMENTS.
VENTILATION:	OBSERVE EPA STANDARDS
PROTECTIVE GLOVES:	FOR SENSITIVE SKIN
EYE PROTECTION:	SAFETY GOGGLES OR FACE SHIELD
OTHERS:	EYE WASH AND SAFETY SHOWER SHOULD BE AVAILABLE
WORK/HYGIENIC PRACTICE:	WASH THOROUGHLY WITH SOAP AND WATER BEFORE EATING, SMOKING OR USING RESTROOM. REMOVE AND WASH CONTAMINATED CLOTHING BEFORE RE-USE.

REVISED: ATO WILBERFORCE

DATE: 7/20/99

WE BELIEVE THE STATEMENTS, TECHNICAL INFORMATION AND RECOMMENDATIONS CONTAINED HEREIN ARE RELIABLE, BUT THEY ARE GIVEN WITHOUT WARRANTY OR GUARANTEE OF ANY KIND, EXPRESS OR IMPLIED, AND WE ASSUME NO RESPONSIBILITY FOR ANY LOSS, DAMAGE, OR EXPENSE, DIRECT OR CONSEQUENTIAL, ARISING OUT OF THEIR USE.